

FAQ

Image overexposed

Issue:

Because the DSM camera can support installation on the front, left side, and right side, and the infrared fill light depends on the installation location, so if the fault installation setting will cause the image to overexposed.

From:

<http://15.188.206.201:8800/> - Europe_Wiki

Permanent link:

<http://15.188.206.201:8800/doku.php?id=public:dashcam:c6d-ai:faq&rev=1632966837>

Last update: **2021/09/30 03:53**

